


**Nurses Office, Teacher's Lounge, Main Office, Principals Office:**

AOC 01 - AOC 02, AOC 04 - AOC 05

Work in area has not begun



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	


SCALE: 1/16" = 1'

**DRAFT** Figure 1.1 - Areas of Concerns

**Assistant Principals Office, Rooms 116 - 120:**

AOC 06, AOC 69 - AOC 70, AOC 72 - AOC 74

Work in area has not begun



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'

**DRAFT** Figure 1.1 - Areas of Concerns

**Rooms 104 - 105:**

AOC 75 - AOC 76


In process of demo: removing existing millwork, wall covers and drywall



Room 105 removal of millwork



Room 105 removal of wall covering



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'

**DRAFT** Figure 1.1 - Areas of Concerns

**Rooms 101 - 103:**

AOC 78 - AOC 81

In process of demo: removing existing millwork, wall covers and drywall



Room 103 Before beginning demo



Room 103 Before beginning demo



**FIRST FLOOR**

**Stark  
Elementary  
School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'


**DRAFT** Figure 1.1 - Areas of Concerns

**Room 157, Rooms 167 - 172**

AOC 83 - AOC 89

Area complete: Millwork reinstalled, drywall repaired, new paint, final clean and turned over

Pictures to be added of finished work



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'


**DRAFT** Figure 1.1 - Areas of Concerns

**Auditorium and Side Area, Auditorium Lobby/ Rear Area:**


AOC 11 - AOC 12

Area complete: Drywall on ceiling demoed and replaced

Picture to be added of finished work



**FIRST FLOOR**



Auditorium Ceiling after Demo

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'


**DRAFT** Figure 1.1 - Areas of Concerns

**Kitchen, Custodial Area, Room 143 (Music Room), P.E. Office:**

**Office:**

AOC 13 - AOC 16

Work in area has not begun



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'

**DRAFT** Figure 1.1 - Areas of Concerns


**Media Center at IT Closet/Entry Door, Media Center and Computer Lab, Media Classroom:**

AOC 17 - AOC 19

Area complete: Drywall replaced, ACT replaced, final clean, and area turned over

Pictures of finished work to be added

AOC 19 (Media Classroom) work yet to begin



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'


**DRAFT** Figure 1.1 - Areas of Concerns



**Cafeteria, Cafeteria Entryway at Teacher's Lounge,  
Gymnasium:**

AOC 03, AOC 09 - AOC 10

Work in area has not begun



**FIRST FLOOR**

**Stark  
Elementary  
School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED:	XX	
APPROVED:	XX	


SCALE: 1/16" = 1'

**DRAFT** Figure 1.1 - Areas of Concerns

**First Floor TLT (Boys Bathroom and Girls Bathroom):**

AOC 07 - AOC 08

Work in area has not begun



**FIRST FLOOR**

**Stark  
Elementary  
School**  
  
City of Stamford  
  
Stamford, CT

MARK	DATE	DESCRIPTION

SCALE: 1/16" = 1'  
**DRAFT** Figure 1.1 - Areas of Concerns

File Saved: 11/19/2018  
Plotted On: Nov 19, 2018 - 11:28am By: wechamps@t  
Tighe & Bond: S:\S2087 - Stamford\033 Mold Remediation - Stamford\033 Mold Remediation - Stamford.dwg


**Corridor b/w 117 - 103, Corridor b/w 105 - Nurse's Office,  
Corridor b/w 101 - 103, Corridor b/w 172 - Main Office:**

AOC 71, AOC 77, AOC 82, AOC 90

Corridor b/w Rm 172 and Main office complete (AOC 90) : Drywall replaced, new paint, final clean, and area turned over

Remaining AOCs work has not begun

Pictures to be added of finished work



**FIRST FLOOR**

**Stark Elementary School**

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION
PROJECT NO:	S2087	
DATE:	11/19/2018	
FILE:	Stark Mold Remediation_recover.dwg	
DRAWN BY:	WAC	
CHECKED BY:	XX	
APPROVED:	XX	

SCALE: 1/16" = 1'

**DRAFT** Figure 1.1 - Areas of Concerns