

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT



| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | | |
|------------------------|-----------------|---|-------------------|------------------------------|--|----------------------------|--------------------------|---|--------------|--------------|------------|----------------|---|--------------------------------|------------------------------------|---------------|---|---|--|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | | |
| Upper Corridor - South | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.4 | 48.2 | 67.9 | | | | | | | | |
| | | PI | VS/NVG | - | No - Only 2 LF cleaned | above ceiling tiles | 48 LF | - | - | | | condensation | DT | Yes - 48 LF of PI disinfected | No | | | | |
| | | DI | VS/NVG | - | - | above ceiling tiles | 10 SF | - | - | | | condensation | DT | Yes - 10 SF of DI disinfected | No | | | | |
| | | CT | NVS/NVG | - | Yes - 5 CT replaced | - | - | - | - | | | | | | | | | | |
| Stairwell B | 10/29/2021 | - | NVS/NVG | - | - | - | - | 8.6 | 48.6 | 70.1 | | | | | | | | | |
| Rm 1 | 10/29/2021 | SR | VS/NVG | Yes - 4 SF of SR disinfected | - | on island | - | - | 9.2 | 33.7 | 72.6 | old staining | | | | | | | |
| | | PI | VS/NVG | Yes - 3 LF of PI disinfected | - | by AHU | - | - | - | | | old staining | | | | | | | |
| | | SB | VS/NVG | Yes - 6 SF of SB disinfected | - | cabinet | - | - | - | | | old staining | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 25 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | high temp concerns | |
| Rm 2 | 10/29/2021 | SR | VS/NVG | - | - | on island | 2 SF | - | 9.5 | 33.9 | 72.3 | condensation | DT | Yes - 2 SF of SR disinfected | No | | | | |
| | | PI | VS/NVG | - | - | by AHU | 2 LF | - | - | | | condensation | DT | Yes - 2 LF of PI disinfected | No | | | | |
| | | CD | NVS/NVG | - | Yes - 25 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | |
| Rm 3 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.5 | 34.6 | 72.3 | | | | | | | | |
| | | PI | VS/NVG | - | Yes - 3 LF cleaned | by AHU | - | - | - | | | old staining | | | | | | | |
| | | CD | VS/NVG | - | 4 diffusers cleaned | cabinet | - | - | - | | | old staining | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 2 SF cleaned | - | - | - | - | | | | | | | | | | |
| Rm 4 | 10/29/2021 | SR | VS/NVG | - | - | on island | 2 SF | - | 9.1 | 32.7 | 72.8 | condensation | DT | Yes - 2 SF of SR disinfected | No | | | | |
| | | PI | VS/NVG | - | - | by AHU | 1 LF | - | - | | | condensation | DT | Yes - 1 LF of PI disinfected | No | | | | |
| | | SB | VS/NVG | Yes - 6 SF of SB disinfected | - | cabinet | - | - | - | | | old staining | | | | | | | |
| | | CD | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | |
| | | SSSS | | | Yes | | | | | | | | | | | | | dehumidifier condensation, mouse droppings, VG on cabinet | |
| Rm 5 | 10/29/2021 | SR | NVS/NVG | Yes - 2 SF of SR disinfected | - | - | - | - | 9.1 | 35.0 | 72.7 | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 4 LF cleaned | - | - | - | - | | | | | | | | | Old heavy staining on FGPI was covered with CP-11 | |
| | | SB | NVS/NVG | Yes - 6 SF of SB disinfected | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | Drain pipe has been replaced. No new staining has been observed | | |
| | | CD | NVS/NVG | - | Yes - 40 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | |
| Rm 6 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.7 | 37.0 | 69.9 | | | | | | | | |
| | | PI | VS/NVG | - | Yes - 3 LF cleaned | by AHU | - | - | - | | | old staining | | | | | | | |
| | | SB | VS/NVG | - | Yes - 4 SF cleaned | cabinet | - | - | - | | | old staining | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 12 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | |
| Rm 7 | 10/29/2021 | SR | VS/NVG | Yes - 2 SF of SR disinfected | - | on island | - | - | 7.8 | 36.0 | 71.8 | old staining | | | | | | | |
| | | PI | VS/NVG | Yes - 3 LF of PI disinfected | - | by AHU | - | - | - | | | old staining | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | cabinet | - | - | - | | | old staining | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 6 SF of CD and 4 diffusers cleaned | - | - | - | - | | | | | | | | | | |
| Copy Room | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.7 | 42.6 | 72.6 | | | | | | | | |
| | | PI | NVS/NVG | Yes - 2 LF of PI disinfected | - | - | - | - | - | | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | |
| Main Office | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.6 | 42.5 | 72.6 | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | |
| | | CT | NVS/NVG | - | Yes - 2 CT replaced | - | - | - | - | | | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT



| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | |
|------------------------|-----------------|--|--------------------|------------------------------|--|---------------------------------------|--------------------------|---|--------------|--------------|--------------------------------------|----------------|---|--------------------------------|--|----------------------|------------------------------|---|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | |
| Asst. Principal Office | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 42.8 | 72.8 | | | | | | | | |
| Principal Office | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 9.2 | 43.4 | 72.7 | | | | | | | | |
| | | Carpet | NVS/NVG | - | - | - | - | 6.2 | | | | | | | | | | |
| Office (storage) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 8.4 | 43.8 | 71.6 | | | | | | | | |
| Conference Room | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 8.6 | 43.4 | 71.1 | | | | | | | | |
| Upper Corridor - East | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 8.7 | 46.6 | 70.1 | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | CT | NVS/NVG | - | Yes - 3 CT replaced | - | - | 6.0 | | | | | | | | | | |
| Rm 8A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 11.2 | 46.2 | 68.0 | | | | | | | | |
| Rm 8B | | SR | NVS/NVG | - | - | - | - | 10.8 | 46.4 | 68.1 | | | | | | | | |
| Rm 8C | | SR | NVS/NVG | - | - | - | - | 9.8 | 47.3 | 68.3 | | | | | | | | |
| Main Lobby | | SR | NVS/NVG | - | - | - | - | - | 45.9 | 68.3 | | | | | | | | |
| Stairwell A | 10/29/2021 | - | NVS/NVG | - | - | - | - | 7.7 | 46.3 | 71.4 | | | | | | | | |
| Vestibule | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 49.7 | 69.2 | | | | | | | | |
| Rm 9 | 10/29/2021 | SR | VS/NVG | - | Yes - 2 SF cleaned | on island | - | 7.7 | 36.7 | 70.8 | old staining | | | | | | | |
| | | PI | VS/NVG | - | Yes - 3 LF cleaned | by AHU | - | - | | | old staining | | | | | | | |
| | | SB | VS/NVG | Yes - 6 SF of SB disinfected | Yes - 6 SF cleaned | cabinet | - | - | | | sink caulking failure / old staining | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 20 SF of CD and 4 diffusers | - | - | - | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | hot & humid |
| Rm 10 | 10/29/2021 | SR | NVS/NVG | - | Yes - 1 SF cleaned | - | - | - | 45.8 | 70.7 | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 4 LF cleaned | - | - | - | | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 1 SF | - | - | - | | | | | | | | | | |
| | | CD | VS/NVG | - | Yes - 40 SF of CD and 4 diffusers | Rust staining on ceiling above wall C | - | - | | | old staining | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | odors, VG, vent condensation | Odor possible from dirty dehumidifier filter. These must be cleaned weekly 10/29. |
| Rm 11 | 10/29/2021 | SR | VS/NVG | Yes - 2 SF of SR disinfected | - | on island | - | 7.2 | 35.6 | 70.5 | old staining | | | | | | | |
| | | PI | VS/NVG | Yes - 2 LF of PI disinfected | - | by AHU | - | - | | | old staining | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | cabinet | - | - | | | old staining | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 20 SF of CD and 4 diffusers | - | - | - | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | hot & humid |
| Rm 12 | 10/29/2021 | SR | NVS/NVG | - | Yes - 1 SF cleaned | - | - | 10.3 | 45.5 | 70.3 | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | Bulletin Brd. | NVS/NVG | - | Yes - 1 SF cleaned | - | - | 12.4 | | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 20 SF of CD and 4 diffusers | - | - | - | | | | | | | | | | |
| SSSS | | | | | | | | | | | | | | | VG on chair, pictures, BB. Teacher is pregnant. 9/20 | No VG on chair 10/29 | | |
| Rm 13 | 10/29/2021 | SR | VS/NVG | - | - | on island | 3 SF | 8.5 | 36.6 | 67.9 | condensation | DT | Yes - 3 SF of SR disinfected | No | | | | |
| | | PI | VS/NVG | - | - | by AHU | 2 LF | - | | | condensation | DT | Yes - 2 LF of PI disinfected | No | | | | |
| | | SB | VS/NVG | Yes - 6 SF of SB disinfected | - | cabinet | - | - | | | old staining | | | | | | | |
| | | Cabinets | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 5 SF of CD and 4 diffusers cleaned | - | - | - | | | | | | | | | | |
| SR | NVS/NVG | - | Yes - 1 SF cleaned | - | - | - | 12.0 | | | | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT

| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | |
|--------------------------|-----------------|---|-------------------|------------------------------|--|--|--------------------------|---|--------------|--------------|------------|--------------------|---|--------------------------------|------------------------------------|---|--------------------------|---|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | |
| Rm 14 | 10/29/2021 | PI | NVS/NVG | - | - | - | - | - | 47.4 | 72.5 | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 2 SF cleaned | Sink bottom | - | - | | | | | | | | | old staining | |
| | | CD | VS/NVG | - | Yes - 10 SF cleaned | Rust staining above wall C | - | - | | | | | | | | | old staining | |
| | | SSSS | | | | | | | | | | | | | | | hot & humid | |
| Rm 15 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 8.8 | 40.8 | 68.7 | | | | | | | | |
| | | PI | VS/NVG | Yes - 3 LF of PI disinfected | - | by AHU | - | - | | | | | | | | | old staining | Old heavy staining on FGPI was covered with CP-11 |
| | | SB | VS/NVG | Yes - 6 SF of SB disinfected | - | cabinet | - | - | | | | | | | | | old staining | |
| | | CD | NVS/NVG | - | Yes - 5 SF cleaned | - | - | - | | | | | | | | | | |
| Rm 17 | 10/29/2021 | SR - wall | NVS/NVG | To be scheduled | To be Scheduled | - | - | 9.7 | 39.0 | 70.5 | | Remove Asbestos SR | To be scheduled | | | previously NE corner SR wet on lower half but no growth or staining | | |
| | | SR - island | NVS/NVG | - | - | - | - | 6.2 | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 15 SF of CD and 4 diffusers | - | - | - | | | | | | | | | | |
| Rm 17A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 7.5 | 38.4 | 71.6 | | | | | | | | |
| Boys RR by Rm 14 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 7.0 | 49.8 | 72.2 | | | | | | | | |
| Girls RR by Rm 19 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 7.1 | 49.6 | 72.2 | | | | | | | | |
| Rm 19 | 10/29/2021 | SR - wall | NVS/NVG | To be scheduled | To be Scheduled | - | - | 7.5 | 44.5 | 71.6 | | Remove Asbestos SR | To be scheduled | | | previously NE corner SR wet on lower half but no growth or staining | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | CD | VS/NVG | - | Yes - 25 SF of CD and 6 diffusers | Rust staining above wall C and teachers desk | - | - | | | | | | | | old staining | | |
| | | SSSS | | | | | | | | | | | | | | hot & humid | | |
| Upper Corridor - North | 10/29/2021 | CT | NVS/NVG | - | Yes - 3 CT replaced | - | - | 6.1 | 36.4 | 71.5 | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | 8.0 | | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 3 LF cleaned | - | - | - | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| Custodian Closet | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 11.3 | 48.8 | 69.8 | | | | | | | | |
| Kiln Room | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 9.6 | 47.8 | 69.8 | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | 6.9 | | | | | | | | | | |
| Rm 16/18 (Nurses Office) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 11.9 | 40.2 | 69.8 | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| Rm 19A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 51.2 | 71.1 | | | | | hot & humid, no ventilation | | | |
| | | SSSS | | | | | | | | | | | | | | | | |
| Portable Corridor | 10/29/2021 | CT | NVS/NVG | - | Yes - 1 CT replaced | - | - | - | 50.5 | 70.1 | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| Portable 1 | 10/29/2021 | CT | NVS/NVG | - | Yes - 4 CT replaced, 2 diffusers cleaned | - | - | - | 44.2 | 70.8 | | | | | | | | |
| | | SR | NVS/NVG | - | Yes - 4 SF cleaned | - | - | - | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | HVAC vents, condensation | |
| | | CT | NVS/NVG | - | Yes - 1 CT replaced, 1 diffuser cleaned | - | - | - | | | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT

| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | | | |
|-------------------|-----------------|--|-------------------|------------------------------------|--|--|--------------------------|---|--------------|--------------|------------|----------------|---|---|------------------------------------|---------------|----------------|--|---|--|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | | | |
| Portable 2 | 10/29/2021 | DI | NVS/NVG | - | - | - | - | - | - | 59.5 | 69.7 | | | | | | | | | |
| | | Objects in room | NVS/NVG | Yes - bookshelf disinfected, books | | - | - | - | - | | | | | | | | | | | |
| | | Vinyl tracks | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | hot & humid. VG on papers, books, & headphones | | |
| Portable 3 | 10/29/2021 | CT | NVS/NVG | - | - | - | - | - | - | 61.0 | 68.5 | | | | | | | | | |
| | | SR | NVS/NVG | Yes - 2 SF of SR disinfected | 10 SF of vinyl wall cleaned | - | - | - | 12.1 | | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | Vents | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | Vinyl tracks | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| Portable 4 | 10/29/2021 | CT | NVS/NVG | - | - | - | - | - | - | 64.3 | 65.5 | | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | 11.7 | | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | Objects in room | VS/VG | - | - | Closet of portable on 2 instrument boxes and green tub | 5 SF | Yes | - | | | | condensation | DT | Yes - 5 SF of objects cleaned | Yes | | | | |
| | | Vinyl tracks | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| SSSS | | | | | | | | | | | | | | odor, ceiling tiles, temp changes throughout the day 9/16 | Musty/mold odor present 10/29 | | | | | |
| Portable 5 | 10/29/2021 | CT | NVS/NVG | - | - | - | - | - | - | 61.1 | 71.2 | | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | 11.4 | | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| Rm 20 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.4 | 36.5 | 71.4 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 2 SF cleaned | cabinet | - | - | - | | | | old staining | | | | | | Old heavy staining on FGPI was covered with CP-11 | |
| | | CD | NVS/NVG | Yes - 2 SF of CD disinfected | - | - | - | - | - | | | | | | | | | | | |
| SSSS | | | | | | | | | | | | | | hot & humid | | | | | | |
| Rm 21 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 11.2 | 53.5 | 72.4 | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 2 LF cleaned | - | - | - | - | | | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 1 SF of CD and 4 diffusers cleaned | - | - | - | - | | | | | | | | | | | |
| Rm 22 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.4 | 33.6 | 73.0 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |
| | | CD | NVS/NVG | Yes - 2 SF of CD disinfected | Yes - 10 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | hot & humid | | |
| Rm 23 | 10/29/2021 | SR | NVS/NVG | - | Yes - 10 SF cleaned | - | - | - | 7.1 | 34.8 | 70.7 | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 4 LF cleaned | - | - | - | - | | | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | | | | |
| | | CD | VS/NVG | - | Yes - 10 SF of CD and 4 diffusers | Rust staining above wall C | - | - | - | | | | old staining | | | | | | | |
| Rm 24 | 10/29/2021 | SR | VS/NVG | - | - | by condensate pump | 2 SF | - | 7.1 | 33.3 | 71.5 | condensation | DT | Yes - 2 SF of SR disinfected | No | | | | | |
| | | PI | VS/NVG | - | - | by AHU | 1 LF | - | - | | | condensation | DT | Yes - 1 LF of PI disinfected | No | | | | | |
| | | SB | VS/NVG | - | - | cabinet | 4 SF | - | - | | | slow leak | DT | Yes - 6 SF of SB disinfected | No | | | | | |
| | | CD | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT



| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | | | | |
|-------------------------------|-----------------|---|-------------------|-----------------------------------|---|----------------------------|--------------------------|---|--------------|--------------|------------|----------------|---|--------------------------------|------------------------------------|---------------|----------------|--------------|---|---------------------------|-----|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | | | | |
| Rm 25 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.6 | 40.1 | 73.3 | old staining | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 5 SF cleaned | - | - | - | - | | | | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 2 SF cleaned | Sink bottom | - | - | - | | | | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 10 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| Boys RR by Rm 25 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.1 | 35.5 | 71.3 | | | | | | | | | | |
| Girls RR by RM 26 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.9 | 35.4 | 71.4 | | | | | | | | | | |
| Rm 26 | 10/29/2021 | SR | VS/NVG | - | Yes - 1 SF cleaned | on island | - | - | 9.8 | 35.6 | 71.4 | old staining | | | | | | | | | |
| | | PI | VS/NVG | - | Yes - 5 LF cleaned | by AHU | - | - | - | | | old staining | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | cabinet | - | - | - | | | old staining | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 60 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | hot & humid | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| Rm 27 | 10/29/2021 | SR | VS/NVG | - | Yes - 2 SF cleaned | on island | - | - | 7.3 | 35.6 | 71.4 | old staining | | | | | | | | | |
| | | PI | VS/NVG | - | Yes - 3 LF cleaned | by AHU | - | - | - | | | old staining | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | cabinet | - | - | - | | | old staining | | | | | | | | | |
| | | Diffuser Vent | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |
| | | CD | NVS/NVG | - | Yes - 25 SF of CD and 4 diffusers | - | - | - | - | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| Rm 28 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.5 | 35.9 | 72.3 | old staining | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |
| | | SB | VS/NVG | Yes - 6 cabinet doors disinfected | - | cabinet | - | - | - | | | | | | | | | | | | |
| | | CD | VS/VG | - | Yes - 10 SF of CD and 4 diffusers | by diffuser | 12 SF | - | - | | | | | | | | | condensation | DT | Yes - 12 SF of CD cleaned | Yes |
| | | | | | | | | | | | | | | | | | | | | | |
| | | | | | | | | | | | | | | | | | | | | | |
| Rm 30A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.9 | 36.9 | 71.8 | | | | | | | | | | |
| Upper Corridor - West | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.5 | 37.9 | 70.7 | | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |
| | | CT | NVS/NVG | - | Yes - 10 CT removed | - | - | - | 6.1 | | | | | | | | | | | | |
| Mens Faculty RR | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 46.2 | 71.3 | | | | | | | | | | | |
| Womens Faculty RR | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 46.0 | 71.0 | | | | | | | | | | | |
| Custodial Closet @ Women's RR | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.5 | 46.3 | 71.2 | | | | | | | | | | |
| Office | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.5 | 46.6 | 71.1 | | | | | | | | | | |
| Rm 28C (Conference Room) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.2 | 47.8 | 70.3 | old staining | | | | | | | | | |
| | | PI | VS/NVG | Yes - 5 LF of PI disinfected | Yes - 3 LF of PI and 1 diffuser cleaned | Near diffuser | - | - | - | | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | | hot & humid, water pooling on CT, moisture on surfaces, VG on | | |
| | | | | | | | | | | | | | | | | | | | | | |
| Room 28A (Psychologist) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.8 | 48.7 | 72.1 | | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | | | hot & humid, poor ventilation, water on floor 9/17 | | |
| Stairwell C | 10/29/2021 | - | NVS/NVG | - | - | - | - | - | 8.3 | 47.2 | 71.0 | | | | | | | | | | |
| Rm 29 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.6 | 48.6 | 72.0 | | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 3 LF cleaned | - | - | - | - | | | | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | - | | | | | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT



| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | |
|--|-----------------|--|-------------------|------------------------------|---|---|--------------------------|---|--------------|--------------|------------|----------------|---|--------------------------------|------------------------------------|--|---|--|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | |
| Rm 30 | 10/29/2021 | CD | NVS/NVG | - | Yes - 60 SF of CD and 4 diffusers | - | - | - | - | 36.8 | 71.0 | condensation | DT | Yes - 2 SF of SR disinfected | No | | | |
| | | SR | VS/NVG | - | - | on island | 2 SF | - | 9.5 | | | condensation | DT | Yes - 2 LF of PI disinfected | No | | | |
| | | PI | VS/NVG | - | - | by AHU | 2 LF | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | | |
| Rm 31 | 10/29/2021 | CD | NVS/NVG | - | 4 diffusers cleaned | - | - | - | - | 42.3 | 70.7 | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | 8.4 | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 3 LF cleaned | - | - | - | - | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | Sink bottom | - | - | - | | | old staining | | | | | | |
| Rm 32 | 10/29/2021 | CD | NVS/NVG | - | Yes - 50 SF of CD and 4 diffusers | - | - | - | - | 36.0 | 71.1 | | | | | hot & humid. VG/VS on deck. Noisy circulator | No VG 10/29 | |
| | | SR | NVS/NVG | - | - | - | - | - | 9.7 | | | | | | | | | |
| | | PI | VS/NVG | - | - | by AHU | 2 LF | - | - | | | condensation | DT | Yes - 2 LF of PI disinfected | No | | | |
| | | SB | VS/NVG | - | - | cabinet | 3 SF | - | - | | | slow leak | DT | Yes - 6 SF of SB disinfected | No | | | |
| Rm 33 | 10/29/2021 | CD | NVS/NVG | - | 4 diffusers cleaned | Celling above wall C | 5 SF | - | - | 42.4 | 72.3 | | | | | hot & humid 9/17. moisture on surfaces. VS on CT. VG on chrome | No VG 10/29 | |
| | | SR | NVS/NVG | - | - | - | - | - | 10.2 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | Sink bottom | - | - | - | | | old staining | | | | | | |
| Rm 34 | 10/29/2021 | CD | NVS/NVG | Yes - 6 SF of CD disinfected | 4 diffusers cleaned | - | - | - | - | 36.5 | 71.7 | | | | | hot & humid | | |
| | | SR | NVS/NVG | - | - | - | - | - | 9.3 | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 2 LF cleaned | - | - | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | | |
| Rm 35 | 10/29/2021 | CD | NVS/NVG | - | Yes - 50 SF of CD and 4 diffusers | - | - | - | - | 44.2 | 73.1 | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | 7.8 | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 6 LF of PI disinfected | - | - | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF of SB disinfected | - | - | - | - | | | | | | | | | |
| Rm 36A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 11.0 | 45.2 | 72.5 | | | | | | | |
| Rm 36 | 10/29/2021 | CD | NVS/NVG | - | Yes - 50 SF of CD and 4 diffusers | - | - | - | - | 36.9 | 71.2 | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | 8.1 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | | |
| Rm 35A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.7 | 39.2 | 70.7 | | | | | | | |
| Rm 37 | 10/29/2021 | CD | VS/NVG | - | Yes - 40 SF of CD and 6 diffusers cleaned | Peeling paint and rust stain in corner of walls B and C | - | - | - | 44.4 | 71.4 | old staining | | | | | | |
| | | SR | NVS/NVG | - | Yes - 2 SF cleaned | - | - | - | 7.9 | | | | | | | | | |
| | | PI | NVS/NVG | - | Yes - 3 LF cleaned | - | - | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | | hot & humid. Moisture on surfaces. Gaps in CD | |
| Custodial @ 1B | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.1 | 39.6 | 70.9 | | | | | | | |
| Teachers' Lounge 1B (Dentist's Office) | 10/29/2021 | SR | | To be Scheduled | To be Scheduled | | | | | | | | Remove Asbestos SR | To be Scheduled | | | No access | |
| | | SB | | | | | | | | | | | | | | | No access | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT



| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments |
|----------------------------|-----------------|--|-------------------|------------------------------|---------------------|----------------------------|--------------------------|---|--------------|--------------|------------|----------------|---|--------------------------------|------------------------------------|---------------|----------------|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | |
| Storage @ 2A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.5 | 38.1 | 70.9 | | | | | | |
| 2A Conference | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.4 | 39.3 | 70.8 | | | | | | |
| Elevator Lobby - Upper | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.4 | 38.2 | 70.7 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.2 | | | | | | | | |
| Middle Corridor - South | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.1 | 36.7 | 71.1 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| Middle Teachers' Lounge 1B | 10/29/2021 | SR | NVS/NVG | - | Yes - 1 CT replaced | - | - | - | 6.3 | 37.6 | 71.4 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.4 | | | | | | | | |
| Mens Faculty RR | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.8 | 37.2 | 71.3 | | | | | | |
| Womens Faculty RR | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.4 | 37.2 | 71.4 | | | | | | |
| Rm 38 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.4 | 35.7 | 71.5 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 2 SF cleaned | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | Yes - 1 CT replaced | - | - | - | 6.2 | | | | | | | | |
| SSSS | | | | | | | | | | | | | | | hot & humid | | |
| Rm 40 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.3 | 36.0 | 71.7 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.0 | | | | | | | | |
| SSSS | | | | | | | | | | | | | | hot & humid, mold smell | | | |
| Rm 42 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.6 | 36.8 | 71.6 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 7.2 | | | | | | | | |
| SSSS | | | | | | | | | | | | | | hot & humid | | | |
| Media Center | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | - | 50.4 | 72.8 | | | | | | |
| | | PI | NVS/NVG | Yes - 2 LF of PI disinfected | - | - | - | - | - | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | Yes - 10/15 | - | - | - | - | - | | | | | | | | |
| Rm 41A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.1 | 47.9 | 69.4 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 8.2 | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | hot & humid | |
| Rm 41B | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 10.4 | 48.3 | 68.8 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 8.0 | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | | hot & humid | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT

| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments |
|----------------------------|-----------------|---|-------------------|-------------------------|--------------------|----------------------------|--------------------------|---|--------------|--------------|------------|----------------|---|--------------------------------|------------------------------------|---------------|----------------|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | |
| Boys Restroom by Rm 44 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.2 | 36.9 | 70.8 | | | | | | |
| Girls Restroom by Rm 44 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.2 | 36.5 | 70.8 | | | | | | |
| Rm 43 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.3 | 48.2 | 73.4 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.7 | | | | | | | | |
| Rm 45 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.8 | 37.7 | 70.8 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 7.0 | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | hot & humid. VG on computers | | |
| Rm 45 Storage | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.9 | 39.6 | 68.2 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | Electronics | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 7.1 | | | | | | | | |
| Rm 44 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.8 | 48.4 | 72.4 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| Middle Corridor - East | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 6.5 | 37.3 | 69.9 | | | | | | |
| Mechanical Room by Stair A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.7 | 38.3 | 69.8 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| Rm 46 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 8.5 | 37.0 | 70.1 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | SB | VS/NVG | - | Yes - 6 SF cleaned | cabinet | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.2 | | | | | | | | |
| | | old staining | | | | | | | | | | | | | | | |
| Rm 47 (Large Storage) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.3 | 36.3 | 70.2 | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.1 | | | | | | | | |
| Rm 48 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 7.3 | 36.8 | 69.8 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | 6.9 | | | | | | | | |
| | | SSSS | | | | | | | | | | | | | hot & humid | | |
| Rm 50 | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | | 43.6 | 69.8 | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | SB | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | - | | | | | | | | | |
| | | SR | NVS/NVG | - | - | - | - | - | 7.7 | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT

| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments | | |
|--------------------------------------|-----------------|--|-------------------|-------------------------|-----------------------------------|----------------------------|--------------------------|---|--------------|--------------|--------------|--------------------|---|--------------------------------|------------------------------------|---------------|--|--|--|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | | | |
| Play Area | 10/29/2021 | PI | NVS/NVG | - | Yes - 25 LF cleaned | - | - | - | 37.1 | 69.9 | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | 6.2 | | | | | | | | | | | |
| Interstitial wall space in play area | 10/29/2021 | PI | NVS/NVG | - | - | - | - | - | 38.8 | 70.0 | | | | | | | | | |
| Rm 49A | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 6.7 | 38.9 | 69.9 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | CT | NVS/NVG | - | - | - | - | 6.1 | | | | | | | | | | | |
| Storage by Rm 49A | 10/29/2021 | SR | - | - | - | - | - | - | - | - | | | | | | | no access | | |
| Small Storage | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 45.2 | 71.0 | | | | | | | | | |
| Mechanical Room (Small) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 45.1 | 72.1 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | CD | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| Mechanical Room (Large) | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 44.7 | 70.7 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | CD | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| Storage by Lg Mech Room | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 9.5 | 45.0 | 71.1 | | | | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | CD | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| Cafeteria | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 17.9 | 43.4 | 69.2 | | | | | | | | | |
| | | CT | VS/NVG | - | - | - | 5 CT | - | | | condensation | R* | To be Scheduled | | | | | | *waiting on replacement tiles, need lift |
| Teachers Dining | 10/29/2021 | SR | VS/NVG | To be Scheduled | To be Scheduled | - | - | - | 42.3 | 70.1 | | Remove Asbestos SR | To be Scheduled | | | | | | |
| | | PI | VS/NVG | - | - | near diffuser | 3 LF | - | | | condensation | DT | Yes - 3 LF of PI disinfected | No | | | | | |
| | | DI | VS/NVG | - | - | near diffuser | 4 SF | - | | | condensation | DT | Yes - 4 SF of DI disinfected | No | | | | | |
| | | CT | NVS/NVG | Yes - 1 CT removed | - | - | - | - | | | | | | | | | | | |
| Café Storage | 10/29/2021 | SR | VS/NVG | - | Yes - 40 drums and parts, 22 hard | Various instrument cases | - | - | 44.2 | 70.3 | old staining | | | | | | | | |
| Kitchen | 10/29/2021 | CT | NVS/NVG | - | - | - | - | 6.3 | 41.2 | 69.3 | | | | 2 CT disinfected by dishwasher | No | | | | |
| | | Freezer door | NVS/NVG | - | Yes - 6 SF cleaned | - | - | - | | | | | | | | | | | |
| Kitchen Electrical | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 7.6 | 42.0 | 68.1 | | | | | | | | | |
| Gym Storage | 10/29/2021 | SR | - | - | - | - | - | - | - | - | | | | | | | no access | | |
| | | PI | - | - | - | - | - | - | | | | | | | | | no access | | |
| Gym | 10/29/2021 | CT | VS/NVG | - | - | - | 18 CT | - | 40.3 | 68.9 | condensation | R* | To be Scheduled | | | | *waiting on replacement tiles, need lift | | |
| P.E. Office | 10/29/2021 | SR | - | - | - | - | - | - | - | - | | | | | | | no access | | |
| Boys RR by PE Office | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 8.2 | 49.3 | 72.8 | | | | | | | | | |
| Girls RR by PE Office | 10/29/2021 | SR | NVS/NVG | - | - | - | - | 7.9 | 49.3 | 72.8 | | | | | | | | | |
| Lower Corridor | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 43.3 | 68.8 | | | | | | | | | |
| Lower Corridor Custodial by Cafe | 10/29/2021 | PI | VS/VG | - | - | by cafeteria | 6 LF | 6.8 | 42.7 | 68.3 | | Remove Asbestos PI | To be Scheduled | | | | | | |
| Custodian Office | 10/29/2021 | SR | VS/NVG | To be Scheduled | To be Scheduled | - | - | 7.1 | 52.2 | 74.1 | | Remove Asbestos SR | To be Scheduled | | | | | | |
| | | PI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |
| | | DI | NVS/NVG | - | - | - | - | - | | | | | | | | | | | |

MOLD ASSESSMENT FIELD NOTES
 TOQUAM MAGNET SCHOOL
 123 RIDGEWOOD AVENUE
 STAMFORD, CONNECTICUT



| Location (Room #) | Assessment Date | Building Materials Impacted SR, CT, PI, DI, SB, CD | Present Condition | Previous Work Completed | | Impacted Material Location | Estimated Quantity of IM | Mold Confirmation Swab Sample Collected | Moisture (%) | Humidity (%) | Temp. (F°) | Suspect Source | AAIS Recommended Response - remove (R), disinfectant treatment (DT) | Remediation Completed (Yes/No) | Post-Clean Swab Collected (Yes/No) | SSSS Comments | T & B Comments |
|---|-----------------|---|-------------------|-------------------------|-----------------|----------------------------|--------------------------|---|--------------|--------------|------------|----------------|---|--------------------------------|------------------------------------|---------------|----------------|
| | | | | 10/22/2021 | 10/4/2021 | | | | | | | | | | | | |
| Boiler Room | 10/29/2021 | SR | VS/NVG | To be Scheduled | To be Scheduled | - | - | - | 7.1 | 50.3 | 76.8 | | Remove Asbestos SR | To be Scheduled | | | |
| | | PI | NVS/NVG | - | - | - | - | - | - | | | | | | | | |
| Generator Room | 10/29/2021 | SR | VS/VG | To be Scheduled | To be Scheduled | - | - | - | 12.1 | 55.2 | 62.4 | | Remove Asbestos SR | To be Scheduled | | | |
| Electrical Room | 10/29/2021 | SR | NVS/NVG | - | - | - | - | - | 9.1 | 51.1 | 72.1 | | | | | | |
| Legend: | | | | | | | | | | | | | | | | | |
| = REQUIRES AAIS RESPONSE ACTION | | | | | | | | | | | | | | | | | |
| = REQUIRES ASBESTOS ABATEMENT | | | | | | | | | | | | | | | | | |
| = SEE SOMETHING SAY SOMETHING LIST | | | | | | | | | | | | | | | | | |
| BOLDED = MEASUREMENT ABOVE INDUSTRY STANDARDS | | | | | | | | | | | | | | | | | |
| SURVEY PERFORMED BY: Randy Taylor and Sawyer Gunnell | | | | | | | | | | | | | | | | | |
| LF = LINEAR FEET, SF = SQUARE FEET, EA = EACH | | | | | | | | | | | | | | | | | |
| R = REMOVAL, DT = DISINFECTANT TREATMENT | | | | | | | | | | | | | | | | | |
| VG = VISIBLE MOLD GROWTH, VS = VISIBLE STAINING, NVG = NO VISIBLE GROWTH, NVS = NO VISIBLE STAINING | | | | | | | | | | | | | | | | | |
| SR = SHEETROCK, CT = CEILING TILE, PI = PIPE INSULATION, FGPI = FIBERGLASS PIPE INSULATION, DI = DUCT INSULATION AHU = AIR HANDLER UNIT, SB = SINK BOTTOM, CD = CEILING DECK SSSS = SEE SOMETHING SAY SOMETHING | | | | | | | | | | | | | | | | | |