





**Legend**

-  THERMOGRAM
- NIC** NOT IN CONTRACT
- +
- +
-  RANDOMLY INTERSPERSED MOISTURE (RIM)
-  SUSPECTED WET INSULATION

<b>Areas:</b>	Total of All Roofs	
	(in approximate square feet)	
	Square Footage of Roof Inspected:	109,153
	Square Footage of Suspected Wet Area:	15,675
	Percentage of Suspected Wet Area:	14.4%
	Square Footage of Suspected RIM Area:	534
	Percentage of Suspected RIM Area:	<1%



**INFRA-RED ROOF MOISTURE ANALYSIS**



**IR ANALYZERS**  
**Vectr Mapping**  
 INFRARED • ELD FUSION™ • NUCLEAR  
 P. (800) 879-1984 • F. 866-536-3522 • email: info@iranalyzers.com  
 NATIONWIDE SERVICE

VIKING CONSTRUCTION  
 BRIDGEPORT, CT  
 STAMFORD HIGH SCHOOL  
 STAMFORD, CT

SCALE:	1/32"=1'-0"
DATE:	06-04-19
PAGE:	1 OF 1
DRAWN BY:	DMR
JOB#:	19231X19