DRAFT Table 1
Areas of Concerns
Rogers International School
302 Blachley Road
Stamford, Connecticut

Tighe&Bond
Engineers | Environmental Specialists

Area of Concern (AOC)	Location	AOC Description	Observations & Comments	Recommendations	Photograph(s)
AOC-01	Stage Storage 167C	Black Growth on Gypsum Wall Board	Black growth on gypsum wall board on north side wall and portions of west side wall (moisture meter readings between 6-8%). North and west walls are located below grade with foundation wall behind gypsum wall. Swab sample of growth collected (Awaiting Results)	Remove growth and gypsum wall board; disinfect and sanitize surfaces/equipment. Retain Architect/Engineer to determine ways to improved ventilation inside the room.	1, 2, 3, 4

LEGEND

SURVEY PERFORMED BY: Francisco J. Rodrigues DATE: November 13, 2018

NOTE: Limited Assessment. Assessment was Not A Full Building Assessment. Areas Assessed Were at Direction of Mold Task Force, Principal, and Custodian