



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4 Wallingford, CT 06492

Tel/Fax: (203) 284-5948 / (203) 284-5978

<http://www.EMSL.com> / wallingfordlab@emsl.com

EMSL Order: 241901898
Customer ID: TIGH62
Customer PO:
Project ID:

Attention: Kevin McCarthy Tighe & Bond 213 Court Street Suite 1100 Middletown, CT 06457	Phone: (860) 704-4760 Fax: (860) 704-4775
Project: 28-2087-033H/ STAMFORD, MOLD TASK FORCE, NORTHEAST- TEACHER'S LOUNGE, SHEETROCK/TAPING COMPOUND	Received Date: 04/17/2019 11:55 AM Analysis Date: 04/17/2019 Collected Date: 04/17/2019

Test Report: Asbestos Fiber Analysis by Transmission Electron Microscopy (TEM) Performed by EPA 40 CFR Part 763 Appendix A to Subpart E

Sample	Location	Volume (Liters)	Area Analyzed (mm ²)	Non Asb	Asbestos Type(s)	#Structures		Analytical Sensitivity (S/cc)	Asbestos Concentration	
						≥0.5μ < 5μ	≥5μ		(S/mm ²)	(S/cc)
041719RT-01C	TEACHER'S LOUNGE-WALL A	1297.20	0.0630	0	None Detected	0	0	0.0047	<16.00	<0.0047
241901898-0001										
041719RT-02C	TEACHER'S LOUNGE-WALL B	1297.20	0.0630	0	None Detected	0	0	0.0047	<16.00	<0.0047
241901898-0002										
041719RT-03C	TEACHER'S LOUNGE-WALL C	1297.20	0.0630	0	None Detected	0	0	0.0047	<16.00	<0.0047
241901898-0003										
041719RT-04C	TEACHER'S LOUNGE-WALL D	1297.20	0.0630	0	None Detected	0	0	0.0047	<16.00	<0.0047
241901898-0004										
041719RT-05C	TEACHER'S LOUNGE-WALL D	1297.20	0.0630	0	None Detected	0	0	0.0047	<16.00	<0.0047
241901898-0005										

Analyst(s)

Almedina Hodzic (5)

Almedina Hodzic, Asbestos Laboratory Manager
or other approved signatory

EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation and use of test results are the responsibility of the client. This report must not be used to claim product certification, approval, or endorsement by NVLAP, NIST, or any agency of the federal government. Results reported in both structures/cm3 and structures/mm2 are dependent on the volume of air sampled and measured by non-laboratory personnel are not the responsibility of EMSL and are not covered by the laboratory's NVLAP accreditation. Samples received in good condition unless otherwise noted. Estimated accuracy, precision and uncertainty data available upon request.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT NVLAP Lab Code 200700-0, NYS ELAP 12063, CT PH-0322, MA AA000191, RI AAL-108T3, VT AL357101

Report amended: 04/17/2019 16:28 PM Replaces amended report from: 04/17/2019 16:25 PM Reason Code: Data Entry-Change to Appearance

TRANSMISSION ELECTRON MICROSCOPY AREA AIR SAMPLING DATA SHEET

Tighe&Bond

241901898

Project Number: 28-2087-033H Date: 4/17/19
 Project Name: Stamford - Mold Task Force - Northeast
 Contractor: AAIS License Number: 017
 Project Monitor: Randy Taylor Project Monitor License Number: 743
 Scope of Work: Teacher's Lounge - Sheetrock/Taping Compound

Sample ID Number	Sample Location	I/O	Sample Time		Sample Duration (Min.)	Flow Rate			Total Volume (Liters)
			On	Off		Pre	Post	Avg.	
041719RT-01C	Teacher's Lounge - Wall A	I	0827	1045	138	9.4	9.4	9.4	1297.2
-02C	-Wall B	I	0828	1046	138	9.4	9.4	9.4	1297.2
-03C	-Wall C	I	0829	1047	138	9.4	9.4	9.4	1297.2
-04C	-Wall D	I	0830	1048	138	9.4	9.4	9.4	1297.2
-05C	-Wall D	I	0831	1049	138	9.4	9.4	9.4	1297.2
-06C	OCB - Decon	O	0833	1051	138	9.4	9.4	9.4	1297.2
-07C		O	0834	1052	138	9.4	9.4	9.4	1297.2
-08C		O	0835	1053	138	9.4	9.4	9.4	1297.2
-09C		O	0836	1054	138	9.4	9.4	9.4	1297.2
-10C		O	0837	1055	138	9.4	9.4	9.4	1297.2
-11C	Field Blank (In)	I							
-12C	Field Blank (Out)	O							
-13C	Sealed Control Blank	---							

Samples Collected By: Randy Taylor Date: 4/17/19 Time: _____
 Samples Rec'd/Sent By: Randy Taylor Date: 4/17/19 Time: _____
 Shipped to: EMSL (State) Lab Drop Off
 Shipment Method: FedEx UPS Overnight UPS Ground Other
 Analysis Method: TEM AHERA Turnaround Time: _____ Special Instructions: _____
 Email to: _____

RECEIVED
 APR 17 2019
 11:55 AM
 [Signature]

Gonzalez, Ivanilly

From: Randy Taylor <MTaylor@TigheBond.com>
Sent: Wednesday, April 17, 2019 12:18 PM
To: Gonzalez, Ivanilly
Subject: Re: Stamford TEM AHERA

Yes it is 6 hour TAT

Get [Outlook for iOS](#)

From: Gonzalez, Ivanilly <igonzalez@EMSL.com>
Sent: Wednesday, April 17, 2019 12:16:07 PM
To: Randy Taylor
Subject: Stamford TEM AHERA

[Caution - External Sender]

Randy,

I know we spoke about 6 hour TEM set but is not noted on the COC. Can you confirm 6 hour TAT?

Thank you
Ivy



Ivanilly Gonzalez | *Administrative Assistant*

EMSL Analytical, Inc. | 29 North Plains Highway, Unit #4 | Wallingford, CT 06492

Phone: 203-284-5948 | Fax: 203-284-5978 | Toll Free: 800-220-3675

Lab Hours: Monday - Friday 8AM - 5:30PM, Saturday-Sunday On-Call

Some of the resources EMSL Analytical, Inc. offers to our clients:

[LABConnect](#) | [Order Products](#) | [Client Corner](#) | [Training](#) | [Additional Resources](#) | [Sampling Videos](#)

"This email may contain privileged and confidential information and is solely for the use of the sender's intended recipient(s). **If you are not the intended recipient of this communication, you are hereby notified that any unauthorized review, use, dissemination, distribution, downloading, or copying of this communication is strictly prohibited.** If you received this email in error, please notify the sender by reply email and delete all copies and attachments. Thank you."