



EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4 Wallingford, CT 06492
Phone/Fax: (203) 284-5948 / (203) 284-5978
<http://www.EMSL.com> / wallingfordlab@emsl.com

Order ID: 241900541
Customer ID: TIGH62
Customer PO:
Project ID: Stamford Mold Task

Attn: Kevin McCarthy
Tighe & Bond
213 Court Street
Suite 1100
Middletown, CT 06457

Phone: (860) 704-4760
Fax: (860) 704-4775
Collected: 01/30/2019
Received: 02/01/2019
Analyzed: 02/04/2019

Proj: 28-2087-033/ STAMFORD MOLD TASK FORCE, ROXBURY E.S. (Stamford Mold Task Force)

Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Swab Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number:	241900541-0001				
Client Sample ID:	0130RT-01				
Sample Location:	GYM-WOOD				
Spore Types	Category	-	-	-	-
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	-	-	-	-	-
Basidiospores	-	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium	-	-	-	-	-
Cladosporium	*Low*	-	-	-	-
Curvularia	-	-	-	-	-
Epicoccum	-	-	-	-	-
Fusarium	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	Medium	-	-	-	-
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	Rare	-	-	-	-
Insect Fragment	-	-	-	-	-
Pollen	-	-	-	-	-
Fibrous Particulate	Low	-	-	-	-

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.
++ = Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.
* = Sample contains fruiting structures and/or hyphae associated with the spores.

Gloria V. Oriol, Microbiology Manager
or Other Approved Signatory

No discernable field blank was submitted with this group of samples.

Samples received in good condition unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation of the data contained in this report is the responsibility of the client.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT AIHA-LAP, LLC--EMLAP Accredited #165118

Initial report from: 02/04/2019 12:04:59

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com

Tighe&Bond

Engineers | Environmental Specialists

241900541

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

SAMPLE LOG FOR MICROBIAL ANALYSIS

Sheet 1 of 1

Project Name: Stamford Mold Task Force

Project No. 28-2087-033

Building: Roxbury E.S.

Project Manager: McCarthy

Sample ID	Sample Type	Sample Location	Material
<u>0130RT-01</u>	<u>SWSB</u>	<u>Gym</u>	<u>wood</u>

Analysis Method: M041 Other Turnaround Time 24 hours

Based on the turnaround time indicated above, analyses are due to Tighe & Bond, Inc. on or before this date: _____
Please call the office if analyses will be late at 860-704-4760.

Email Results to: kmccarthy@tighebond.com Do Not Mail Hard Copy Report Total # of Samples: 1

Special Instructions: M041 Analysis - Fungal Direct Identification. Note Project Specific Sample Rates

Samples collected by: Randy Taylor Date: 01/30/19 Time: _____

Samples [Rec'd][Sent by] [] [] Date: [] [02/01/19] Time: _____

Samples Received by: _____ Date: _____ Time: _____

Shipped To: EMSL State CT Other _____

Method of Shipment: Fed Ex Other Drop off

