

Stillmeadow

- Mold Task Force Spreadsheets
 - [Active spread sheet of work being conducted](#)
 - [Swab test results spread sheet](#)
- School has been assigned to Viking Construction and BBS A/E
- KMK Insulators performed a site visit to evaluate sweating pipe and condensation issues at the school
- Portables will require TEMPORARY repairs that will need to be maintained yearly if new portables are not installed.
- Infra-Red Analyzers performed an infrared [roof scan](#) and [report](#) of the school.

If you have any additional questions, please email

Moldtaskforce@stamfordct.gov