

Hart Magnet Elementary School

Summary of Work: March 27, 2019

Active spreadsheet of work being conducted in areas of concern posted on City website under school page. Please [CLICK HERE](#) to view the active sheet.

- **Silver Petrucelli**- conducted a full site visit. [Report](#) posted on website.
- **Swing Space**- Two rooms, Media Center and Science room will be used as swing spaces.
- **Room 40**- Work in room 40 has been completed.
- **Windows**- Similar issues with failing caulking at Newfield were found at Hart. Caulk was tested for PCBs, results will be posted on website.
- **Pipe Wrapping**- Pipe insulation also does not have a proper vapor barrier. The vapor barrier for pipes is a 6ml plastic lining that is placed between the pipe and insulation. Will need to determine if insulation size is adequate for heating pipes.