RED HATCH

Remove Mold Impacted/Water Damaged Fiberglass Pipe Insulation.
Conduct Work in a Work Constructed of Criticals and Negative Pressure.
Following Removal Clean Entire Area with Shockwave.



Hart Magnet Elementary School

City of Stamford

Stamford, CT

MARK	DATE	DESCRIPTION

PROJECT NO:	S2087
DATE:	11/19/2018
FILE:	Hart Mold Remediation.dwg
DRAWN BY:	WAC
CHECKED:	XX
APPROVED:	XX

SCALE: 1/16" = 1'

Last Saved: 11/19/2018
Plotted On:Nov 19, 2018-3:26pm By: wachampagne
Tighe & Bond: J:\S\S2087 Stamford\033 Mold Remediation Consulting\Sites\Hart Magnet\Drawings\CAD\Hart Mold Remediation.dwg