

KT Murphy

- Skylights - Will be a summer project, glass will need to be ordered soon. Wood framing around skylights is impacted by mold and will need to be replaced in summer as well.
- Waiting for Roof scan report to determine fix for leaks in book room.
- Sump pump and Sewer Ejector pump
 - Design to come June 1st project completed this summer
- Corridor- 10-12
 - Hallways and skylights- this summer
 - Classrooms – Summer 2020