



# EMSL Analytical, Inc.

29 North Plains Highway, Unit # 4 Wallingford, CT 06492  
Phone/Fax: (203) 284-5948 / (203) 284-5978  
<http://www.EMSL.com> / [wallingfordlab@emsl.com](mailto:wallingfordlab@emsl.com)

Order ID: 241806090  
Customer ID: TIGH62  
Customer PO:  
Project ID: Stamford Mold Task

**Attn:** Kevin McCarthy  
Tighe & Bond  
213 Court Street  
Suite 1100  
Middletown, CT 06457

Phone: (860) 704-4760  
Fax: (860) 704-4775  
Collected: 11/16/2018  
Received: 11/20/2018  
Analyzed: 11/20/2018

**Proj:** 28-2087-033/ STAMFORD MOLD TASK FORCE, ALTERNATE ROOTS-LEAP (Stamford Mold Task Force)

## Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Swab Samples (EMSL Method MICRO-SOP-200)

<b>Lab Sample Number:</b>	241806090-0001				
<b>Client Sample ID:</b>	1116KM01				
<b>Sample Location:</b>	ROOM 1 (LARRY LOUNGE) CEILING TILE-BLACK				
<b>Spore Types</b>	<b>Category</b>	-	-	-	-
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	-	-	-	-	-
Basidiospores	-	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium	-	-	-	-	-
Cladosporium	-	-	-	-	-
Curvularia	-	-	-	-	-
Epicoccum	-	-	-	-	-
Fusarium	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	-	-	-	-	-
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	-	-	-	-	-
Insect Fragment	-	-	-	-	-
Pollen	-	-	-	-	-
Fibrous Particulate	Low	-	-	-	-

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.  
++ = Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.  
\* = Sample contains fruiting structures and/or hyphae associated with the spores.

Gloria V. Oriol, Microbiology Manager  
or Other Approved Signatory

No discernable field blank was submitted with this group of samples.

Samples received in good condition unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. Interpretation of the data contained in this report is the responsibility of the client.

Samples analyzed by EMSL Analytical, Inc. Wallingford, CT AIHA-LAP, LLC--EMLAP Accredited #165118

Initial report from: 11/20/2018 17:48:10

For Information on the fungi listed in this report please visit the Resources section at [www.emsl.com](http://www.emsl.com)



Engineers | Environmental Specialists

241806090

213 Court Street, Suite 1100, Middletown, CT 06457

Phone 860-704-4760

**SAMPLE LOG FOR MICROBIAL ANALYSIS**

Sheet 1 of 1

Project Name: Stamford Mold Task Force

Project No. 28-2087-033

Building: Alternate Roots - LEAP

Project Manager: McCarthy

Sample ID	Sample Type	Sample Location	Material
1116 KM 01	SWAB	Room 1 (LARRY lounge) Ceiling Tile	Black growth

Analysis Method:  M041  Other Turnaround Time 24 hrs

Based on the turnaround time indicated above, analyses are due to Tighe & Bond, Inc. on or before this date: \_\_\_\_\_  
Please call the office if analyses will be late at 860-704-4760.

Email Results to: kmccarty@tighebond.com **Do Not Mail Hard Copy Report** Total # of Samples: 1

Special Instructions: M041 Analysis - Fungal Direct Identification. Note Project Specific Sample Rates

Samples collected by: [Signature] Date: 11/16/18 Time: Pm

Samples [Rec'd][Sent by] [Signature] Date: 11/19/18 || 11/20/18 Time: Am/Am

Samples Received by: \_\_\_\_\_ Date: \_\_\_\_\_ Time: \_\_\_\_\_

Shipped To:  EMSL State CT  Other \_\_\_\_\_

Method of Shipment:  Fed Ex  Other Drop

