





-  → KNOWN AREAS w/ growth As of 11/19/18
-  → NEW AREAS w/ growth IDENTIFIED 11/20/18
-  → AREA Imp. 11/20/18



FIRST FLOOR

Stark Elementary School
City of Stamford
Stamford, CT

| MARK | DATE | DESCRIPTION |
|------|------|-------------|
| | | |
| | | |
| | | |
| | | |
| | | |

| | |
|-------------|------------------------------------|
| PROJECT NO: | S2087 |
| DATE: | 11/19/2018 |
| FILE: | Stark Mold Remediation_recover.dwg |
| DRAWN BY: | WAC |
| CHECKED: | XX |
| APPROVED: | XX |

SCALE: 1/16" = 1'
DRAFT Figure 1.1 - Areas of Concerns

Last Saved: 11/19/2018 11:51 AM By: wachsmayer
 Tighe & Bond J:\552087\Stark\03 Mold Remediation\Consulting\Stark\Drawings\CAD\Stark Mold Remediation - Recover.dwg