

## Springdale

- Mold Task Force Active Spreadsheets
  - [Work Being Conducted](#)
  - [Swab Test Results](#)
- Roof
  - Infra-Red Analyzers
    - [Roof Scan](#)
    - [Report](#)
  - Gottfried
    - [Roof Assessment](#)
- [Water Testing](#)
  - Incoming potable water tested within healthy limits.
- 6 fans have been rented and installed by Viking Construction to assist in improving air circulation over the summer.

If you have any additional questions, please email

**[SAMG@stamfordct.gov](mailto:SAMG@stamfordct.gov)**