EMSL Analytical, Inc.
29 North Plains Highway, Unit # 4 Wallingford, CT 06492
Phone/Fax: (203) 284-5948 / (203) 284-5978
http://www.EMSL.com / wallingfordlab@emsl.com

Order ID:	241902708
Customer ID:	TIGH62
Customer PO:	28-2087-033
Project ID:	Stamford Mold Task

Attn:	Kevin McCarthy	Phone:	(860) 704-4760
	Tighe & Bond	Fax:	(860) 704-4775
	213 Court Street	Collected:	05/29/2019
	Suite 1100	Received:	05/30/2019
	Middletown, CT 06457	Analyzed:	05/30/2019

Proj: 28-2087-033/STAMFORD MOLD TASK FORCE/TURN OF RIVER MIDDLE SCHOOL (Stamford Mold Task Force)

Test Report: Microscopic Examination of Fungal Spores, Fungal Structures, Hyphae, and Other Particulates from Swab Samples (EMSL Method MICRO-SOP-200)

Lab Sample Number:	241902708-0001				
Client Sample ID:	529KM02				
Sample Location:	BASEMENT CORRIDOR-CEILING TILE				
Spore Types	Category	-	-	-	-
Alternaria (Ulocladium)	-	-	-	-	-
Ascospores	-	-	-	-	-
Aspergillus/Penicillium	*High*	-	-	-	-
Basidiospores	Rare	-	-	-	-
Bipolaris++	-	-	-	-	-
Chaetomium	-	-	-	-	-
Cladosporium	Low	-	-	-	-
Curvularia	-	-	-	-	-
Epicoccum	Rare	-	-	-	-
Fusarium	-	-	-	-	-
Ganoderma	-	-	-	-	-
Myxomycetes++	Rare	-	-	-	-
Pithomyces++	-	-	-	-	-
Rust	-	-	-	-	-
Scopulariopsis/Microascus	-	-	-	-	-
Stachybotrys/Memnoniella	-	-	-	-	-
Unidentifiable Spores	-	-	-	-	-
Zygomycetes	-	-	-	-	-
Hyphal Fragment	Low	-	-	-	-
Insect Fragment	-	-	-	-	-
Pollen	-	-	-	-	-
Fibrous Particulate	Medium	-	-	-	-

Category: Count/per area analyzed - Rare: 1 to 10 Low: 11 to 100 Medium: 101 to 1000 High: >1000

- Denotes Not Detected.
++ = Includes other spores with similar morphology; see EMSL's fungal glossary for each specific category.
* = Sample contains fruiting structures and/or hyphae associated with the spores.

No discernable field blank was submitted with this group of samples.

Gloria V. Oriol, Microbiology Manager
or Other Approved Signatory

Samples received in good condition unless otherwise noted. EMSL maintains liability limited to cost of analysis. This report relates only to the samples reported above and may not be reproduced, except in full, without written approval by EMSL. EMSL bears no responsibility for sample collection activities or analytical method limitations. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the results, it will be noted on the report. Interpretation of the data contained in this report is the responsibility of the client. The report reflects the samples as received. When the information supplied by the customer can affect the validity of the result, it will be noted on the report.

Samples analyzed by EMSL Analytical, Inc of Wallingford, CT AIHA-LAP, LLC-EMLAP Accredited #165118

Initial report from: 05/31/2019 08:42:12

For Information on the fungi listed in this report please visit the Resources section at www.emsl.com

OrderID: 241902708

Tighe&Bond
Engineers | Environmental Specialists

241902708

213 Court Street, Suite 1100, Middletown, CT 06457 Phone 860-704-4760

SAMPLE LOG FOR MICROBIAL ANALYSIS

Project Name: Stamford Mold Task Force Project No. 28-2087-033

Building: Turn of River Middle School Project Manager: McCarthy

Sample ID	Sample Type	Sample Location	Material
529KM02	Swab	Basement Corridor – Ceiling Tile	Black Growth

Analysis Method: ☒ M041 ☐ Other Turnaround Time 24 hr.

Based on the turnaround time indicated above, analyses are due to Tighe & Bond, Inc. on or before this date: _____ Please call the office if analyses will be late at 860-704-4760.

Email Results to: kmccarthy@tighebond.com **Do Not Mail Hard Copy Report** **Total # of Samples:** _____

Special Instructions: M041 Analysis – Fungal Direct Identification. Note Project Specific Sample Rates

Samples collected by: McCarthy **Date:** 5/29/19 **Time:** PM

Samples [Rec'd][Sent by] [McCarthy][McCarthy] **Date:** [5/30/19][5/30/19] **Time:** AM

Samples Received by: _____ **Date:** _____ **Time:** _____

Shipped To: ☒ EMSL State CT ☐ Other _____

Method of Shipment: ☐ Fed Ex ☒ Other Drop

RECEIVED
MAY 30 2019
By (9 9:10am)
WB