

## Stamford High School

### Summary of Work: March 13, 2019

Active spreadsheet of work being conducted in areas of concern posted on City website under school page. Please [CLICK HERE](#) to view the active sheet.

- **Viking Construction**- The school has been assigned to Viking Construction for managing all further work in school.
- **AAIS Phase 1 Restoration**- AAIS to commence phase 1 surface cleaning this week.
- **Front of Building**- Roof issues and water leaks around windows were examined by Tighe and Bond. Similar issues found at Newfield and Hart
- **Lower Level/Media Center**- Damage from old flood, need to examine space more thoroughly.
- **Middle Building**- Dirty diffusers were examined as well as some water leaks.