

## **Stamford High School**

- Tucker Mechanical to assess belimo valves in Stamford High and Stillmedow. It is suspected that valves have failed at Stamford high school because of spikes in water temperature. Replacement project to be planned.
- Tighe and Bond in process of creating a cleaning plan for Stamford High School, focusing this summer on 1927 building.
- Areas of Concern that will need to be addressed
  - 1927 Building – Exploring possibility of closing for the summer to perform work above plaster ceilings, the plywood structure above ceiling and floor.
  - 600 Wing
    - 10,000 feet of sheetrock with Asbestos taping.
  - Boyle Stadium
    - Locker Room
- City to engage structural engineer that has done prior work in the building.