Tighe&Bond


Client: City of Stamford Mold Task Force

Site: CLC Lockwood Ave

**Job Number:** 28-2087-033U

Photograph No.: 1 Date: 5/13/19 Direction Taken: NA

Description: Entry—Water Damaged/Growth Impacted Drywall



Tighe&Bond

Client: City of Stamford Mold Task Force

Job Number: 28-2087-033U

Site: CLC Lockwood Ave

Photograph No.: 3 Date: 5/13/19 Direction Taken: NA

**Description:** Electrical Room—Water Stained Ceiling Tiles



Photograph No.: 4 Date: 5/13/19 Direction Taken: NA

**Description:** Electrical Room—Open PVC Drain



Tighe&Bond

Client: City of Stamford Mold Task Force Job Number: 28-2087-033U

Site: CLC Lockwood Ave

Photograph No.: 5 | Date: 5/13/19 | Direction Taken: NA

**Description:** Janitor Closet—Water Stained Ceiling Tile



Photograph No.: 6 Date: 5/13/19 Direction Taken: NA

**Description:** Room 17 Closet—Bucket with Water from Leak





Client: City of Stamford Mold Task Force

Site: CLC Lockwood Ave

Job Number: 28-2087-033U

**Photograph No.:** 7 **Date:** 5/13/19 **Direction Taken: NA Description:** Room 17—Active Leak from Roof Leader



