


Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: S-2087-033

Photograph No.: 1 Date: 11/13/18 Direction Taken: —

Description: Stained ceiling tiles— Apples Assessment Room



Tighe&Bond

Job Number: <u>S</u>-2087-033

Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Photograph No.: 3 | Date: 11/13/18 | Direction Taken: -

Description: Stained ceiling tile — Apples Assessment Room



Photograph No.: 4 Date: 11/13/18 Direction Taken: —

Description: Typical Window— Apples Assessment Room







Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: S-2087-033






Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: <u>S-2087-</u>033



Photograph No.: 8 Date: 11/13/18 Direction Taken: —

Description: Water damaged gym ceiling—Gymnasium



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: S-2087-033

Photograph No.: 9 Date: 11/13/18 Direction Taken: —

Description: Water damaged gym ceiling—Gymnasium



Photograph No.: 10 Date: 11/13/18 Direction Taken: —

Description: Stained metal roof deck—Gymnasium






Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: <u>S-2087-</u>033





Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: S-2087-033

Photograph No.: 13 Date: 11/13/18 Direction Taken: —

Description: Stained Tectum roof deck—Science Storage Room (2nd Floor)

Photograph No.: 14 Date: 11/13/18 Direction Taken: —

Description: Water damaged floor—Auditorium Lobby



Tighe&Bond

Client: City of Stamford Mold Task Force

Site: Rippowam Middle School

Job Number: S-2087-033

Photograph No.: 15 Date: 11/13/18 Direction Taken: —

Description: Water damaged floor—Auditorium Lobby

