

Westhill Pool and Café Update



Installed new pool and café air handling units, piping and duct insulation. Pool air handler equipped with de-humidifier.

Café unit is providing heating and ventilation.



Installed new pool condensing unit for new de-humidifier



Installed new pool outdoor air energy recovery unit to temper outside air for energy savings required by energy code

Westhill Pool and Café Update



Pool drained and scaffolding erected for ceiling tile replacement, grand stand lighting replacement and installation of new returned air ductwork .

Preparation for abatement



Pool ceiling removal and replacement